
# Ethernet shield for Arduino<sup>®</sup>







#### Configure your Arduino<sup>™</sup> as a simple web server or let it get data from the worldwide web.

#### Features

- For use with Arduino Uno<sup>™</sup>, Arduino Mega<sup>™</sup>
- Based on Microchip ENC28J60
- · IEEE 802.3 compatible Ethernet controller
- Integrated MAC & 10BASE-T PHY
- SPI interface
- With RJ45 connector

#### Specifications

- · Max. clock speed: 20MHz
- Transmit/receive buffer: 8kB
- Dimensions: 68 x 53mm / 2.67 x 2.08"







# assembly hints

#### 1. Assembly (Skipping this can lead to troubles ! )

Ok, so we have your attention. These hints will help you to make this project successful. Read them carefully.

#### 1.1 Make sure you have the right tools:

- · A good quality soldering iron (25-40W) with a small tip.
- Wipe it often on a wet sponge or cloth, to keep it clean; then apply solder to the tip, to give it a wet look. This is called 'thinning' and will protect the tip, and enables you to make good connections. When solder rolls off the tip, it needs cleaning.
- . Thin raisin-core solder. Do not use any flux or grease.
- A diagonal cutter to trim excess wires. To avoid injury when cutting excess leads, hold the lead so they cannot
  fly towards the eyes.
- · Needle nose pliers, for bending leads, or to hold components in place.
- · Small blade and Phillips screwdrivers. A basic range is fine.
- For some projects, a basic multi-meter is required, or might be handy

#### 1.2 Assembly Hints :

- · Make sure the skill level matches your experience, to avoid disappointments.
- · Follow the instructions carefully. Read and understand the entire step before you perform each operation.
- · Perform the assembly in the correct order as stated in this manual
- · Position all parts on the PCB (Printed Circuit Board) as shown on the drawings.
- · Values on the circuit diagram are subject to changes, the values in this assembly guide are correct\*
- · Use the check-boxes to mark your progress.
- · Please read the included information on safety and customer service

\* Typographical inaccuracies excluded. Always look for possible last minute manual updates, indicated as 'NOTE' on a separate leafle

#### 1.3 Soldering Hints :


- 1. Mount the component against the PCB surface and carefully solder the leads
- 2. Make sure the solder joints are cone-shaped and shiny
- 3. Trim excess leads as close as possible to the solder joint












TOU


STRIPF 4TH 1%


-1 000 00

# DO NOT BLINDLY FOLLOW THE ORDER OF THE COMPONENTS ONTO THE TAPE, ALWAYS CHECK THEIR, VALUE ON THE PARTS LIST!

### Construction









- 6 -





□ C5 : 470µF

□ C6 : 10µF □ C9 : 470µF



GK6: 2 x 3p

(Cros)





SK5








Watch the position of the notch!

□ IC2: 74HC125




## II CONNECTION DIAGRAM




### DOWNLOAD SAMPLE CODE FROM KA04 PAGE ON WWW.VELLEMAN.BE
















The new Velleman Projects catalogue is now available. Download your copy here: <u>www.vellemanprojects.eu</u>



Modifications and typographical errors reserved - © Velleman nv. HKA04'IP (Rev.1) Velleman NV, Legen Heirweg 33 - 9890 Gavere.

