



Run Mode :

- ◇ Impuls at input : IN-'UP' (count up) or IN-'Down' (count down).
- ◇ Change actual counter UP/DOWN with Up-Down keys Hold for High Speed Scrolling.
- ◇ Press ENTER for counter reset "0000" or load the preset value (L Pr)

